

5 April 2023

Randwick City Council 30 Frances Street Randwick NSW 2031

Attention: Ryan Zammit

ryan.zammit@randwick.nsw.gov.au

RE: Asbestos Containing Material Clearance Inspection

Dear Ryan Zammit

Please find below Asbestos Containing Material Clearance Inspection results for the following site:

Site:	Little Bay Beach		
Location:	Southern, Western and Northern Little Bay Beach		

All works have been completed in accordance with applicable WHS Legislation, Approved Codes of Practice and Australian Standards

Regards,

Wajid Mahmood

Occupational Hygienist Licensed Asbestos Assessor 002010













Requested by:					
Name	Ryan Zammit				
Contact	90936744				
Email	ryan.zammit@randwick.nsw.gov.au				
Site Details:					
Address	2 Coast Hospital Rd, Little Bay NSW 2036				
Local Government Area	Randwick City Council				



Clearance Area					
Clearance Type:					
Clearance Type	Asbestos Containing Material				
Application Legislation	 - 2011 WHS Act - 2017 WHS Regulations - SafeWork NSW Code of Practice, How to Manage and Control Asbestos in the Workplace 2019 - SafeWork NSW Code of Practice, How to Safely Remove Asbestos 2019 				













	- Guidance Note On	The Membrane Filter Method For Estimating			
	Airborne Asbestos Fibres 2nd Edition [Nohsc:3003(2005)]				
Scope of Remediation World		k / /d			
Location of Remediation	ation of Remediation Southern Western and Northern Little Boy Reach				
Work	Southern, Western and Northern Little Bay Beach				
Material	FC Sheeting				
Bonded / Friable	Non-Friable				
Scope of Remediation		ected ACM fragments from sand surface			
Date of Remediation work	05/04/2023				
Documents Reviewed	NA				
Remediation Contractor	NA				
License Number	NA				
Contact Number	NA				
Clearance Inspection:					
Time	09:00	09:00			
Date	05/04/2023				
Consultant	Wajid Mahmood				
Consultant	Licensed Asbestos A	Assessor 002010			
	The inspection found NO VISIBLE ASBESTOS remaining in areas				
	outlined in the removal scope. Visually, all identified asbestos-containing				
Result/s	materials had been removed from the identified areas. The removal area				
	and immediate surrounds have been cleaned to a practically achievable				
	standard with no visible asbestos residue.				
Notes Nil					
Enclosure Smoke Test:	1				
Date – Location – Result	N/A	N/A			
Air Monitoring:	T				
Date - Type - Result		05/04/2023 - Background - All air monitoring results were below the			
	exposure standard of 0.01 f/ml				
Sampling:	1.1/4				
Date – Type – Result	N/A				
Photos:	10 4				
Prior to Remediation	See Appendix 1				
Post Remediation	See Appendix 2				
Disclaimer:					
The results within this report relate only to the sampling locations specified and their analysis. This report					
shall not be reproduced, except in full.					
Prepared By:	Approved By:				
Ship of ships		Whole I			
Wajid Mahmood Denny Bolatti					
Occupational Hygienist		Principal Occupational Hygienist			
Licensed Asbestos Assessor	002010	Licensed Asbestos Assessor 001132			
05/04/2023		08/05/2023			













Appendix 1 – Photos Prior to Remediation



Notes: Overview of suspected FC Sheeting fragment within Northern Beach.



Notes: Overview of suspected FC Sheeting fragment within Northern Beach.



Notes: Overview of suspected FC Sheeting fragment within Northern Beach.



Notes: Overview of suspected FC Sheeting fragment within Northern Beach.













Notes: Overview of suspected FC Sheeting fragment within Northern Beach.



Notes: Overview of suspected FC Sheeting fragment within Northern Beach.



Notes: Overview of suspected FC Sheeting fragment within Western Beach.



Notes: Overview of suspected FC Sheeting fragment within Western Beach.













Notes: Overview of suspected FC Sheeting fragment within Western Beach.



Notes: Overview of suspected FC Sheeting fragment within Western Beach.



Notes: Overview of suspected FC Sheeting fragment within Western Beach.













Appendix 2 – Photos Post Remediation



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.













Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Northern Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Western Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Western Beach.















Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Western Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Western Beach.



Notes: Visual surface clearance inspection following emu picking of suspected FC Sheeting fragment within Western Beach.













Appendix 3 - Clearance Certificate

Dear Ryan Zammit,

Pursuant to Clause 473 NSW Work Health and Safety Regulation 2017, Trinitas Group was engaged as an Occupational Hygienist to conduct a Clearance Inspection as required

The evidence to form a determination as to whether the Asbestos Containing Material remediation area is safe for normal use included the verification methods as outlined within clause 473 (3) of the NSW Work Health and Safety Regulation 2017.

I, Wajid Mahmood, an Occupational Hygienist of Trinitas Group Pty Ltd affirms that I undertook the Clearance Inspection. I am satisfied that the remediation area and area immediately surrounding it, are free from visual contamination.

Pursuant to clause 474 (5) of the NSW Work Health and Safety Regulation 2017, I state that, I, Wajid Mahmood, Occupational Hygienist, found no visible residue from remediation works in the area, or in the vicinity of the area, where the work was carried out.

Based on the verification methods required by the NSW Work Health and Safety Regulation 2017 Clause 473 the remediation area does not pose a risk to health and safety from exposure to Asbestos Containing Material during normal use.

Upon receipt of this Clearance Certificate, the remediation area may be re-occupied.

Regards,

Wajid Mahmood

Occupational Hygienist Licensed Asbestos Assessor 002010















How to Contact Us

Mail Trinitas Group

PO Box 1376 Parramatta NSW 2124

Email <u>admin@trinitasgroup.com.au</u>

Address Level 3, 24 Hunter Street, Parramatta NSW 2150

Website www.trinitasgroup.com.au

Telephone 1800 4 TRINITAS
Facsimile 02 8016 0875

Trinitas Group Pty Ltd

ABN 12 161 759 708

Disclaimer: This report is prepared for the use of the recipient for the purpose of risk evaluation, risk improvement and or loss control. It is based upon prevailing conditions at the time of inspection, our observations and information provided by the client contact/s at the site. No responsibility is accepted, and liability disclaimed for the use of this report for any other purpose, or by any third party, nor does it imply that no other hazardous conditions exist.









