Asbestos Containing Material Clearance Inspection

1 September 2022

Randwick City Council
30 Frances Street
Randwick NSW 2031

Attention: Joe Santangelo
joe.santangelo@randwick.nsw.gov.au

RE: Asbestos Containing Material Clearance Inspection

Dear Joe Santangelo

Please find below Asbestos Containing Material Clearance Inspection results for the following site:

Site:	Little Bay Beach
Location:	Southern, Western and Northern Little Bay Beach

All works have been completed in accordance with applicable WHS Legislation, Approved Codes of Practice and Australian Standards

Regards,

Karim Nazemi
Senior Occupational Hygienist
Licensed Asbestos Assessor #001359

Requested by:	
Name	Joe Santangelo
Contact	0436839760
Email	joe.santangelo@randwick.nsw.gov.au
Site Details:	
Address	2 Coast Hospital Rd, Little Bay NSW 2036
Local Government Area	Randwick City Council

Clearance Area	
Clearance Type:	
Clearance Type	Asbestos Containing Material
Application Legislation	- 2011 WHS Act - 2017 WHS Regulations - SafeWork NSW Code of Practice, How to Manage and Control Asbestos in the Workplace 2019 - SafeWork NSW Code of Practice, How to Safely Remove Asbestos 2019

	- Guidance Note On The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [Nohsc:3003(2005)]
Scope of Remediation Work:	
Location of Remediation Work	Southern, Western and Northern Little Bay Beach
Material	FC fragments
Bonded / Friable	Non-Friable
Scope of Remediation	Emu picking of suspected ACM Fragments from sand surfaces
Date of Remediation work	01/09/2022
Documents Reviewed	Nil
Remediation Contractor	-
License Number	-
Contact Number	-
Clearance Inspection:	
Time	13:47
Date	01/09/2022
Consultant	Karim Nazemi Senior Occupational Hygienist
Result/s	The inspection found NO VISIBLE ASBESTOS remaining in areas outlined in the removal scope. Visually, all identified asbestos-containing materials had been removed from the identified areas. The removal area and immediate surrounds have been cleaned to a practically achievable standard with no visible asbestos residue.
Notes	Nil
Enclosure Smoke Test:	
Date – Location – Result	N/A
Air Monitoring:	
Date – Type – Result	01/09/2022 - Background – All results below the exposure standards
Sampling:	
Date – Type – Result	N/A
Photos:	
Prior to Remediation	See Appendix 1
Post Remediation	See Appendix 2

Disclaimer:

The results within this report relate only to the sampling locations specified and their analysis. This report shall not be reproduced, except in full.

Prepared By:	**Approved By:**
Karim Nazemi *Licensed Asbestos Assessor #001359* Senior Occupational Hygienist 01/09/2022	**Denny Bolatti** Principal Occupational Hygienist Licensed Asbestos Assessor 001132 05/09/2022

Appendix 1 – Photos Prior to Remediation

Notes: FC fragment identified on sand surface prior to emu pick - Southern section

Notes: FC fragment identified on sand surface prior to emu pick - Southern section

Notes: FC fragment identified on sand surface prior to emu pick - Southern section

Notes: FC fragment identified on sand surface prior to emu pick - Southern section

Notes: FC fragment identified on sand surface prior to emu pick - Southern section	**Notes:** FC fragment identified on sand surface prior to emu pick - Northern section
Notes: FC fragment identified on sand surface prior to emu pick - Northern section	**Notes:** FC fragment identified on sand surface prior to emu pick - Northern section

 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section
 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section

 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section
 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section

 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section
 Notes: FC fragment identified on sand surface prior to emu pick - Northern section	 **Notes:** FC fragment identified on sand surface prior to emu pick - Northern section

Appendix 2 – Photos Post Remediation

Notes: Sand surface following emu pick - Southern section

Notes: Sand surface following emu pick - Southern section

Notes: Sand surface following emu pick - Southern section



Notes: Sand surface following emu pick - Southern section

 Notes: Sand surface following emu pick - Southern section	 **Notes:** Sand surface following emu pick - Northern section
 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section

 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section
 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section

 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section
 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section

 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section
 Notes: Sand surface following emu pick - Northern section	 **Notes:** Sand surface following emu pick - Northern section

Appendix 3 - Clearance Certificate

Dear Joe Santangelo,

Pursuant to Clause 473 NSW Work Health and Safety Regulation 2017, Trinitas Group was engaged as a Licensed Asbestos Assessor #001359 to conduct a Clearance Inspection as required

The evidence to form a determination as to whether the Asbestos Containing Material remediation area is safe for normal use included the verification methods as outlined within clause 473 (3) of the NSW Work Health and Safety Regulation 2017.

I, Karim Nazemi, a Licensed Asbestos Assessor #001359 of Trinitas Group Pty Ltd affirms that I undertook the Clearance Inspection. I am satisfied that the remediation area and area immediately surrounding it, are free from visual contamination.

Pursuant to clause 474 (5) of the NSW Work Health and Safety Regulation 2017, I state that, I, Karim Nazemi, Licensed Asbestos Assessor #001359, found no visible residue from remediation works in the area, or in the vicinity of the area, where the work was carried out.

Based on the verification methods required by the NSW Work Health and Safety Regulation 2017 Clause 473 the remediation area does not pose a risk to health and safety from exposure to Asbestos Containing Material during normal use.

Upon receipt of this Clearance Certificate, the remediation area may be re-occupied.

Regards,

Karim Nazemi
Licensed Asbestos Assessor #001359
Senior Occupational Hygienist

How to Contact Us

Mail	Trinitas Group
	PO Box 1376 Parramatta NSW 2124
Email	admin@trinitasgroup.com.au
Address	Level 3, 24 Hunter Street, Parramatta NSW 2150
Website	www.trinitasgroup.com.au
Telephone	1800 4 TRINITAS
Facsimile	02 8016 0875

Trinitas Group Pty Ltd
ABN 12 161 759 708

Disclaimer: This report is prepared for the use of the recipient for the purpose of risk evaluation, risk improvement and or loss control. It is based upon prevailing conditions at the time of inspection, our observations and information provided by the client contact/s at the site. No responsibility is accepted, and liability disclaimed for the use of this report for any other purpose, or by any third party, nor does it imply that no other hazardous conditions exist.