17 May 2021

Randwick City Council
30 Frances Street
Randwick NSW 2031

Attention: Ryan Zammit
ryan.zammit@randwick.nsw.gov.au

RE: Asbestos Containing Material Clearance Inspection

Dear Ryan Zammit

Please find below Asbestos Containing Material Clearance Inspection results for the following site:

Site:	Little Bay Beach

All works have been completed in accordance with applicable WHS Legislation, Approved Codes of Practice and Australian Standards

Regards,

Melody Mohammadi
Occupational Hygienist
MEng Environmental Pollution Control

Requested by:	
Name	Ryan Zammit
Contact	90936744
Email	ryan.zammit@randwick.nsw.gov.au
Site Details:	
Address	2 Coast Hospital Rd, Little Bay NSW 2036
Local Government Area	Randwick City Council

Clearance Area	
Clearance Type:	
Clearance Type	Asbestos Containing Material
Application Legislation	2011 WHS Act 2017 WHS Regulations Code of Practice, How to Manage and Control Asbestos in the Workplace 2019 Code of Practice, How to Safely Remove Asbestos 2019 Guidance Note On The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [Nohsc:3003(2005)]
Scope of Remediation Work:	
Location of Remediation Work	Southern, western and northern Little Bay Beach
Material	Bonded asbestos

Bonded / Friable	Non-Friable
Scope of Remediation	Emu picking of suspected fragments on sand surfaces
Date of Remediation work	17/05/2021
Documents Reviewed	NA
Remediation Contractor	NA
License Number	NA
Contact Number	NA
Clearance Inspection:	
Time	10:00
Date	17/05/2021
Consultant	Melody Mohammadi MEng Environmental Pollution Control
Result/s	The inspection found NO VISIBLE ASBESTOS remaining in areas outlined in the removal scope. Visually, all identified asbestos-containing materials had been removed from the identified areas. The removal area and immediate surrounds have been cleaned to a practically achievable standard with no visible asbestos residue.
Notes	NA
Enclosure Smoke Test:	
Date	N/A
Location	N/A
Results	N/A
Air Monitoring:	
Date – Type – Result	17/05/2021 - Background - All results < 0.01 f/ml
Sampling:	
Date – Type – Result	N/A
Photos:	
Prior to Remediation	See Appendix 1
Post Remediation	See Appendix 2

Disclaimer

The results within this report relate only to the sampling locations specified and their analysis. This report shall not be reproduced, except in full.

Prepared By	Approved By
Melody Mohammadi *Occupational Hygienist* MEng Environmental Pollution Control 17/05/2021	**Denny Bolatti** Managing Director Licensed Asbestos Assessor LAA001132 15/06/2021

Appendix 1 – Photos Prior to Remediation

 Notes: Overview of Southern beach during low tide	 **Notes:** Overview of Western beach during low tide
 Notes: Overview of Northern beach during low tide	 **Notes:** Overview of the removal item within northern beach

Notes: Overview of the removal item within western beach

Appendix 2 – Photos Post Remediation

Notes: Visual inspection of the removal item within northern beach area following removal	**Notes:** Visual inspection of the removal item within western beach area following removal

Appendix 3 - Clearance Certificate

Dear Ryan Zammit,

Pursuant to Clause 473 NSW Work Health and Safety Regulation 2017, Trinitas Group was engaged as an Occupational Hygienist to conduct a Clearance Inspection as required

The evidence to form a determination as to whether the Asbestos Containing Material remediation area is safe for normal use included the verification methods as outlined within clause 473 (3) of the NSW Work Health and Safety Regulation 2017.

I, Melody Mohammadi, a Occupational Hygienist of Trinitas Group Pty Ltd affirms that I undertook the Clearance Inspection. I am satisfied that the remediation area and area immediately surrounding it, are free from visual contamination.

Pursuant to clause 474 (5) of the NSW Work Health and Safety Regulation 2017, I state that, I, Melody Mohammadi, Occupational Hygienist , found no visible residue from remediation works in the area, or in the vicinity of the area, where the work was carried out.

Based on the verification methods required by the NSW Work Health and Safety Regulation 2017 Clause 473 the remediation area does not pose a risk to health and safety from exposure to Asbestos Containing Material during normal use.

Upon receipt of this Clearance Certificate, the remediation area may be re-occupied.

Regards,

Melody Mohammadi
Occupational Hygienist
MEng Environmental Pollution Control

How to Contact Us

Mail	Trinitas Group
	PO Box 1376 Parramatta NSW 2124
Email	admin@trinitasgroup.com.au
Address	Level 3 Hunter Street, Parramatta NSW 2150
Website	www.trinitasgroup.com.au
Telephone	1800 4 TRINITAS
Facsimile	02 8016 0875

Trinitas Group Pty Ltd
ABN 12 161 759 708

Disclaimer: This report is prepared for the use of the recipient for the purpose of risk evaluation, risk improvement and or loss control. It is based upon prevailing conditions at the time of inspection, our observations and information provided by the client contact/s at the site. No responsibility is accepted, and liability disclaimed for the use of this report for any other purpose, or by any third party, nor does it imply that no other hazardous conditions exist.