

Precinct resolution

PRECINCT: Matraville Precinct

EMAIL: matprecinct@gmail.com

**MEETING
DATE:** 08 July 2024

FILE: F2006/00657

ACTIONED TO: Tony Lehmann, Manager Integrated Transport

**RESOLUTION
NUMBER:** **Resolution 08072024(1)**

Resolution

Resolution 08072024(1)– Raised concern of way to have a traffic calming solution, especially at the crest of the hill at Jersey Road.

Council to look at ways to slow the traffic as appears without the use of the speed humps. E.g. Traffic island traffic survey at this spot as well as remark the lines on the road. Speed on Jersey Road with the crest of the hill asked if we place a resolution to council on way to slow the traffic down, especially with increase children using park and playground at the Des Renford Leisure Centre.

Council response

Arrangements have been made for the undertaking of pneumatic tube traffic counts, adjacent to nos 17, 43 and 73 Jersey Road (see location map overleaf). A pneumatic tube traffic counter is a device used to count and measure traffic on roads. They're connected to a small equipment box, on the side of the road.

Pneumatic tube traffic counters provide the following information:

- How many vehicles passed
- When they passed
- How fast they were going
- What direction they were going
- What types of vehicles they were

These traffic counters should be installed this week by contractors. We expect the results to be forwarded to the Council by the end of the month. Once we have this data we will prepare a report for the Traffic Committee. We will also inform the Precinct of the results and likely next steps.

Council contact

Tony Lehmann

Manager Integrated Transport
19 May 2025



Precinct resolution

PRECINCT: Matraville Precinct **EMAIL:** matprecinct@gmail.com

MEETING DATE: 08 July 2024 **FILE:** F2006/00657

ACTIONED TO: Tony Lehmann, Manager Integrated Transport

RESOLUTION NUMBER: **Resolution 08072024(2)**

Resolution

Resolution 08072024(2) – Raise again the Australia Ave, intersection at Bunnerong Road, asked council to review to have a NO UTURN signed erected. Ask council to be proactive as there has been many near misses as advised by residents. Rather be proactive then reactive which we believe council are being. Simple sign will stop any chance of an accident.

Council response

An examination of over six years of reported crash data has revealed that there has been only a single reported collision at the Bunnerong Road / Australia Avenue intersection. At 9:31pm on 5 March 2019, a 19 year old local male, driving a car northbound, lost control and ran off Bunnerong Road to the left. The road was dry. This incident was not associated with a turning manoeuvre.

Notwithstanding the above advice, as Bunnerong Road is a State Road, managed by Transport for NSW (TfNSW), the Precinct's request has been forwarded to TfNSW for consideration.

Once a response is received from TfNSW the Precinct will be informed.

Council contact

Tony Lehmann

Manager Integrated Transport
19 May 2025