

Air Monitoring Certificate



Clearsafe Environmental Solutions Pty Ltd
9 Industrial Road, Unanderra NSW 2526
info@clearsafe.com.au
1300 042 962

Report Number: 40-15092-14-AM
Monitoring Date: 18/11/2022
Received Date: 18/11/2022
Analysis Date: 18/11/2022
Report Date: 18/11/2022
Site Address: 307-327R Fitzgerald Avenue
Maroubra NSW 2035

Client Contact: Blain Knox
Sampled By: Gonzalo Serna Diaz
Approved Counter: Keanen Richardson
Approved Signatory: Luke Heckenberg

Client Name: Noble Works Australia Pty Ltd
Client Address: 47 George St
Clyde NSW 2142

Test Method: Airborne fibre monitoring in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC:3003(2005)] and Clearsafe method SOP.AM.01.

Notes: The results contained within this report relate only to the samples tested. This report should not be copied, presented or reviewed except in full.

Sample Number	Location	Code*	Time		Airflow		Fibres	Fields	Conc.**
			On	Off	On	Off			
40-15092/74	Western boundary fence	1	07:00	15:00	1.01	1.01	0	100	<0.01
40-15092/75	Northern boundary fence	1	07:03	15:03	1.01	1.01	0	100	<0.01
40-15092/76	Eastern boundary fence	1	07:05	15:06	1.01	1.01	1	100	<0.01
40-15092/77	Southern boundary fence	1	07:07	15:09	1.01	1.01	0	100	<0.01
40-15092/78	Field Blank	6					0	100	N/A

** Concentration in Fibres/mL of air

* Sample Codes:

- 1 - Asbestos removal
- 2 - Bag-out
- 3 - Enclosure dismantling
- 4 - Clearance
- 5 - Background
- 6 - Blank Sample
- 7 - Fibre Count Only
- 8 - Personal monitoring

40-15092-14-AM



NATA Accredited Laboratory No. 18542

Accredited for compliance with ISO/IEC 17025 - Testing. The results of the tests, calibrations and/or measurements included in this document are traceable to Australian / national standards.