

JBS&G (68409 - 164,578)

AMR001 Airborne Asbestos Fibre Monitoring Report, Finucane Reserve (Rev 0)

20 December 2024

Noah Walsh-Gay Randwick City Council Via email: noah.walsh-gay@randwick.nsw.gov.au

AMR001: Airborne Asbestos Fibre Monitoring Report Finucan Reserve, 1 Finucane Crescent Matraville, NSW

Dear Noah,

Please find as **Attachment 1**, the airborne asbestos fibre monitoring results for works associated with Finucane Reserve, located at 1 Finucane Crescent, Matraville NSW (the site) on **Wednesday 18 December 2024.**

All air monitoring was completed in accordance with the *Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres* [NOHSC: 3003(2005)], with NATA certification applying to all sample collection, handling, and analytical procedures.

All reported results were satisfactory and conform with the minimum action level of 0.01 fibres /mL for control monitoring as outlined in:

- Work, Health and Safety (2017) Regulation; and
- Safework NSW (2022) Code of Practice How to Safely Remove Asbestos.

If you have any questions regarding these results, please feel free to contact the undersigned on 02 8245 0300 or by email mnoujaim@jbsg.com.au.

Yours sincerely:

M.Noujaim

Milad Noujaim Environmental Consultant SafeWork NSW Licensed Asbestos Assessor (LAA 002002) JBS&G Australia Pty Ltd





1 Asbestos Air Monitoring Results

©JBS&G Australia Pty Ltd



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 8, 179 Elizabeth St Sydney

NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025—Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Page 1 of 6

Report Number: 1173285-AFC

Isaac Lee Attention: Report 1173285-AFC **Project Name MATRAVILLE**

Project ID 68409

Received Date Dec 19, 2024 Dec 19, 2024 **Date Reported**

METHODOLOGY:

Date Reported: Dec 19, 2024

Sampling as per the National Occupational Health & Safety Commission - Guidance Asbestos Sampling

Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and the NATA Specific Accreditation Criteria, ISO/IEC 17025 Application Document Life Sciences – Annex, Asbestos sampling and testing,

Issued: March 2022.

Pump Calibration Air sampling pump performance has been assessed in accordance with Australian

Institute of Occupational Hygiene (AIOH) Technical Paper Air Sampling Pumps: Equipment Calibration Requirements. Pump flow rate measurement equipment (e.g. Field Rotameter) has been calibrated in accordance with AIOH Technical Paper Flow

Measurement Equipment: Calibration Requirements.

Fibre counting is conducted in accordance with the National Occupational Health & Asbestos Counting

Safety Commission Guidance Note on the Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition, [NOHSC:3003(2005)] (MFM) and supplementary work instruction in-house LTM-ASB-8010. Unless specifically noted, analysis is

undertaken by approved analysts at the base facility. Fibre counts (Fibres/fields) are covered by the facility's NATA scope of accreditation. The requirements of the NATA Specific Accreditation Criteria, ISO/IEC 17025 Application Document Life Sciences –

Annex, Asbestos sampling and testing, Issued: March 2022 are realised.

ABN: 50 005 085 521 Telephone: +61 2 9900 8400



Project Name MATRAVILLE

Project ID 68409

Date SampledDec 18, 2024Report1173285-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
24-De0051789	DI466187	AC018	SOUTHERN FENCE	8:12	16:03	1.5	1.5	0/100	< 0.01
24-De0051790	DI466211	AC159	WESTERN FENCE	8:15	16:05	1.5	1.5	0/100	< 0.01
24-De0051791	DI466248	AC195	NORTHERN FENCE	8:18	16:08	1.5	1.5	0/100	< 0.01
24-De0051792	DI466293	AC096	EASTERN FENCE	8:21	16:12	1.5	1.5	0/100	< 0.01
24-De0051793	DI466249	BLANK	BLANK					0/100	

Report Number: 1173285-AFC



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

DescriptionTesting SiteExtractedHolding TimeAsbestos - LTM-ASB-8010SydneyDec 19, 2024Indefinite

Report Number: 1173285-AFC



email: EnviroSales@eurofinsanz.com

Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521

Melbourne 6 Monterey Road Dandenong South VIC 3175 +61 3 8564 5000 NATA# 1261

Site# 1254

Geelong Sydney 19/8 Lewalan Street Grovedale Girraween VIC 3216 NSW 2145 +61 3 8564 5000 NATA# 1261 NATA# 1261 Site# 25403

Canberra 179 Magowar Road Unit 1.2 Dacre Street Mitchell ACT 2911 +61 2 9900 8400 +61 2 6113 8091 NATA# 1261 Site# 18217 Site# 25466

Asbestos Fibre Count & Concentration

5

Brisbane 1/21 Smallwood Place Murarrie QLD 4172 T: +61 7 3902 4600 NATA# 1261 Site# 20794 & 2780

Newcastle 1/2 Frost Drive Mavfield West NSW 2304 +61 2 4968 8448 NATA# 1261 Site# 25079

ABN: 91 05 0159 898 Perth

Eurofins ARL Pty Ltd

46-48 Banksia Road Welshpool WA 6106 +61 8 6253 4444 NATA# 2377 Site# 2370 & 2554

Eurofins Environment Testing NZ Ltd NZBN: 9429046024954

Auckland

Penrose.

35 O'Rorke Road

Auckland 1061

+64 9 526 4551

IANZ# 1327

Auckland (Focus) Unit C1/4 Pacific Rise. Mount Wellington, Auckland 1061 +64 9 525 0568 IAN7# 1308

Received:

Christchurch 43 Detroit Drive Rolleston. Christchurch 7675 +64 3 343 5201 IAN7# 1290

Dec 19, 2024 5:45 PM

Tauranga 1277 Cameron Road. Gate Pa, Tauranga 3112 +64 9 525 0568 IAN7# 1402

Company Name: Address:

web: www.eurofins.com.au

JBS & G Australia (NSW) P/L Level 8, 179 Elizabeth St

Sydney NSW 2000

Project Name: Project ID:

MATRAVILLE 68409

Order No.:

Report #: 1173285 02 8245 0300

Phone: Fax:

Dec 19, 2024 Due: Priority: Same day Contact Name: Isaac Lee

Eurofins Analytical Services Manager: Andrew Black

Sample Detail

Х Sydney Laboratory - NATA # 1261 Site # 18217 **External Laboratory** Sample Date Sample ID Sampling LAB ID No Matrix Time Χ DI466187 4:03PM Air S24-De0051789 Dec 18, 2024 S24-De0051790 DI466211 Dec 18, 2024 4:05PM Air Χ 3 DI466248 Dec 18, 2024 4:08PM Air S24-De0051791 Χ DI466293 Dec 18, 2024 4:12PM Air S24-De0051792 Χ 5 DI466249 Dec 18, 2024 Air S24-De0051793 Χ

Test Counts



Internal Quality Control Review and Glossary General

QC data may be available on request.

All soil results are reported on a dry basis, unless otherwise stated.

Samples were analysed on an 'as received' basis.

Information identified on this report with the colour blue indicates data provided by customer that may have an impact on the results

5. This report replaces any interim results previously issued

Holding Times

Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

Units

Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w) Airborne fibre filter loading as Fibres (N) per Fields counted (n) Airborne fibre reported concentration as Fibres per millilitre of air drawn over the sampler membrane (C) % w/w

F/fld

F/mL

Mass, e.g. of whole sample (\mathbf{M}) or asbestos-containing find within the sample (\mathbf{m}) Concentration in grams per kilogram Volume, e.g. of air as measured in AFM ($\mathbf{V} = \mathbf{r} \times \mathbf{t}$) g, kg

g/kg

L, mL

Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r) Time (t), e.g. of air sample collection period L/min

min

Calculations

 $C = \left(\frac{A}{a}\right) \times \left(\frac{N}{p}\right) \times \left(\frac{1}{p}\right) \times \left(\frac{1}{t}\right) = K \times \left(\frac{N}{p}\right) \times \left(\frac{1}{p}\right)$ Airborne Fibre Concentration:

Asbestos Content (as asbestos): $\% w/w = \frac{(m \times P_A)}{M}$ Weighted Average (of asbestos): $\%_{WA} = \sum_{r} \frac{(m \times P_A)_x}{r}$

Terms

COC

HSG248

PCM

Sampling

Date Reported: Dec 19, 2024

Estimated percentage of asbestos in a given matrix may be derived from knowledge or experience of the material, informed by HSG264 Appendix 2, else

assumed to be 15% in accordance with WA DOH Appendix 2 (PA). This estimate is not NATA-accredited

ACM Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the

NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.

ΑF Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable

material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable"

AFM Airborne Fibre Monitoring, e.g., by the MFM.

Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004. Amosite

AS

Asbestos Content (as asbestos) Total %w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).

Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004... Chrysotile

Chain of Custody

Crocidolite

Crocidolite Asbestos Detected. Crocidolite may also refer to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 5370:2024* Sampling and

qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004...

Sample is dried by heating prior to analysis. Dry

DS Dispersion Staining. Technique required for unequivocal Identification of asbestos fibres by PLM.

FA Fibrous Asbestos, Asbestos-containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become

friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to distinguish visibly and may be assessed as AF.

Fibre Count Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003

Fibre Identification. Unequivocal identification of asbestos fibres according to AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials Fibre ID

(ISO 22262-1:2012, MOD), formerly AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos

Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is Friable

outside of the laboratory's remit to assess the degree of friability UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021), ISBN: 9780616667079.

HSG264 UK HSE HSG264, Asbestos: The Survey Guide (2012), .ISBN: 9780717665020

ISO (also ISO/IEC) International Organization for Standardization / International Electrotechnical Commission.

Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece K Factor

graticule area of the specific microscope used for the analysis (a).

LOR

MFM (also NOHSC:3003) Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane

Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].

Man-Made Vitreous Fibre - exhibiting isotropic characteristics, including glass fibres, glass wool, rock wool, slag wool, ceramic fibres and "bio-soluble fibres. MMVF

NOTE: previously known as "synthetic mineral fibre" (SMF)

NEPM (also ASC NEPM) National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended)

Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004.. Organic

Phase Contrast Microscopy. This is used for fibre counting according to the MFM.

Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 5370:2024* Sampling and qualitative identification of asbestos in PLM

bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004. Unless otherwise stated, Eurofins are not responsible for sampling equipment or the sampling process.

SRA Sample Receipt Advice

Trace Analysis An analytical procedure is used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.

UK HSE HSG United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.

Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according to AS 5370:2024* UMF

Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004.. It may include (but is not limited to)

actinolite, anthophyllite, or tremolite asbestos.

WA DOH Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-

Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis

Weighted Average Combined average %w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA)

> Eurofins Environment Testing 179 Magowar Road, Girraween NSW, Australia, 2145 Page 5 of 6 ABN: 50 005 085 521 Telephone: +61 2 9900 8400 Report Number: 1173285-AFC



Comments

Volume Measurement: FINN BILLYARD CURREY, JBS & G Australia (NSW) P/L, has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]methodology. Sampling pumps used by JBS & G Australia (NSW) P/L were calibrated by Eurofins Environment Testing and therefore volume measurements contained in this report are traceable back to Eurofins Environment Testing. Eurofins Environment Testing are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Geronimo Jr Abrot Senior Analyst-Asbestos

Authorised by:

Sayeed Abu Senior Analyst-Asbestos

Glenn Jackson
Managing Director

Final Report - this report replaces any previously issued Report

- Indicates Not Requested
- * Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please $\underline{\text{click here.}}$

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Page 6 of 6

Report Number: 1173285-AFC

Date Reported: Dec 19, 2024

ABN: 50 005 085 521 Telephone: +61 2 9900 8400